


235.08:20-08:46 Several brief periods (2m, 6m, 2m, 2m) of 1024bps RT data lost due to problems with uplink transfer between DSS14 and DSS16. DR G100248 refers.

236.13:27-16:00 2h33m RT 1024bps data degraded 10% at DSS65. No DR.



239.00:12-00:19 7m RT 1024bps data lost at DSS54 following unknown glitch after new predicts load. No DR.

237.12:43-13:24 41m 1024bps RT data lost at DSS65 following predict problems. DR M100129 refers.

237.13:29-17:39 4h10m RT 1024bps data degraded 7% at DSS65 No DR.